

BUILDING SAFETY CERTIFICATE

APPENDIX X

No.

Dated:

Certified that the Nar Yug Public School Hamidpur (name of the building or premises) at Hamidpur Block Tappal Aligarh (address) comprised of basement(s) and

..... (upper floors) owned/occupied by All of Satisfactory (name of the

Institution) have complied with the Building Bye Laws in accordance with rule of State/UT, and incorporate the provisions of building safety as specified in National Building Code 2005, 2016 and as amended thereafter and has been verified by the concerned officer on 25/11/17 (date of inspection) in the presence of Manager Nar Yug Public School Hamidpur (name and addresses of the Manager/Secretary or his representative) and that the said above building/premises is safe and fit for running School with effect from for a period of years in accordance with rules.

Issued on 25/11/17 at by

* Strike out whichever is not applicable.

Signature with Seal:

Authority:

Designation:

(Er. S. A. Khan)
J.E.R.E.S.
Block-Tappal (Aligarh)

To Manager

Nar Yug Public School
Hamidpur Tappal

(Name & Address of the Institution)

ENDORSEMENT

The No Objection Certificate issued by department stand cancelled and annulled due to

..... (reasons to be recorded)
(Er. S. A. Khan)
J.E.R.E.S.
Block-Tappal (Aligarh)

(Name and designation of the authorized signatory)

नवयुग पब्लिक स्कूल हामिदपुर तहसील खैर जिला अलीगढ़ के भवन की स्थिति
विद्यालय भवन की जांच के अन्तर्गत दो मंजिल भवन की बिन्दु बार आख्या निम्नवत है :-

क्र०सं०	विद्यालय भवन की जांच हेतु बिन्दु	आख्या
1.	विद्यालय भवन की अद्यतन स्थिति	सन्तोष जनक
2.	विद्यालय भवन में पेयजल की स्थिति	सन्तोष जनक
3.	विद्यालय में पहुंचने हेतु सम्पर्क मार्ग की स्थिति	सन्तोष जनक

उपरोक्त विद्यालय भवन प्रथम दृष्टया नेशनल बिल्डिंग कोड-2005 के मानकों के
अनुरूप विद्यालय भवन वर्तमान में सुरक्षित एवं सन्तोषजनक हैं।

सहायक अभियन्ता
प्रा०ख० लो०नि०वि० अलीगढ़।

1. जिला विद्यालय निरीक्षक, अलीगढ़ के पत्र के सन्दर्भ में आवश्यक कार्यवाही हेतु प्रेषित।

सहायक अभियन्ता
प्रा०ख० लो०नि०वि० अलीगढ़।

(ऋतुराज सिंह)
सहायक अभियन्ता
प्रान्तीय खण्ड लोक निर्माण विभाग
अलीगढ़

क0स0	विद्यालय भवन की जांच हेतु बिन्दु	आख्या
1.	विद्यालय भवन की अद्यतन स्थिति	सन्तोष जनक
2.	विद्यालय भवन में पेयजल की स्थिति	सन्तोष जनक
3.	विद्यालय में पहुंचने हेतु सम्पर्क मार्ग की स्थिति	सन्तोष जनक

सहायक अभियन्ता
प्रा०ख० लो०नि०वि० अलीगढ़।
(शत्रु राज सिंह)
सहायक अभियन्ता
प्रा०नि०य०ख० लो०नि०वि० अलीगढ़।
(शत्रु राज सिंह)

सहायक अभियन्ता
प्रा०ख० लो०नि०वि० अलीगढ ।